

# CITY OF SAINT PAUL, MN

## DEPARTMENT OF SAFETY AND INSPECTIONS

Steve Magner, Manager of Code Enforcement

Truth-in-Sale of Housing Report

375 Jackson Street, Suite 220 Saint Paul, MN 55101-1806 Phone: 651-266-8989 Fax: 651-266-1919 Web: <u>www.stpaul.gov/dsi</u>

This is a visual disclosure report based on the current City of Saint Paul Truth-in-Sale of Housing Evaluator Guidelines and is valid for one year from the date of issuance and for the owner named.

Property Address: 1880 MONTREAL AVE

Date of Evaluation: Sep 4, 2019 Date of Expiration: Sep 03, 2020

This report is intended to provide basic information to the home buyer and seller prior to the time of sale.

This report WILL NOT be used to enforce the requirements of the Legislative Code; however, it will be used to determine if there is compliance with the requirements for sale within the City of Saint Paul, MN.



### **MAJOR NOTIFICATIONS AND WARNINGS**

For questions on these items, call the City's Information and Complaint Line at 651-266-8989

Residential Type: Single Family Dwelling

#### Smoke Detectors:

- Smoke Detector Present: Y
- Smoke Detector Properly Located: Y
- Smoke Detector Hard Wired (required in Single Family Homes): Y
- Smoke Detector Comments:

#### Open Permits:

This property has the following open permits:

B - 14 353266 - - Active/Issued

B - 18 111444 - GARAGE REMODEL. ADD GABLE END - Inspected

# **HAZARDOUS**

# Garage(s)/ Accessory Structure(s

• Electrical wiring, outlets and fixtures

# **BELOW MINIMUM**

# **Basement Only**

• Electrical service installation/grounding

### Basement/ Cellar

· Stairs and Handrails

# Bathroom(s)

· Electrical outlets and fixtures

## **Exterior Space**

• Open porches, stairways and deck(s)

# Garage(s)/ Accessory Structure(s

· Sab condition

# Hallways, Stairs and Entries

• Stairs and handrails to upper floors

# Sleeping Room(s)

• Window size and openable area

Report Rating Key (Where there as	n to which a Comment is related)		
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

## CITY OF SAINT PAUL TRUTH- IN- SALE OF HOUSING REPORT

Address: 1880 MONTREAL AVE Date of Evaluation: Sep 4, 2019

Zoning District: R3 Present Occupancy:

Number of Units Evaluated: Single Family

Dwelling

File Number: File#: 19-080819

Owner: Patricia Connelly Client Name: Pat Connelly Client Contact: 612.242.9152

Evaluator Name: Doug Hastings Cities' Inspectio

Evaluator Contact: Work: 952-892-0490

1. low handrail & ends not returned to wall

julie@citiesinspection.com

### Basement/ Cellar

1. Stairs and Handrails В

2. Basement/Cellar Floor

3. Foundation NV

4. Evidence of Dampness or Ν Staining

5. First Floor, Floor System М

6. Beams and Columns М

#### **Electrical Services**

7a. Number of Electrical Services 1

7b. Amps 100

7c. Volts 120-240

### **Basement Only**

8. 日ectrical service installation/grounding

В M

М

8. incomplete panel index

9. 日ectrical wiring, outlets and fixtures

Plumbing System

10. Floor drain(s) (basement) М

11. Waste and vent piping (all М

floors)

12. Water piping (all floors) М

13. Gas piping (all floors) М

14. Water heater(s), installation M

15. Water heater(s), venting M

16. Plumbing fixtures М

(basement)

### **Heating System(s)**

The Evaluator is not required to operate the heating plant(s) except during the heating season, between October 15 and April 15.

17a. Number of Heating

Systems

17b. Type Forced Air

17c. Fuel Gas

Evaluator: Doug Hastings Cities' Inspection Service

1880 MONTREAL AVE Sep 4, 2019 Page # 3

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related)					
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum		
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable		

Y: Yes	I: No		NV: Not Visible	NA: Not Applicable
<ul><li>18. Installation and visible condition</li><li>19. Viewed in operation (required in heating season)</li><li>20. Combustion venting</li></ul>		M N M		
21a. Additional heatir Type 21b. Additional heatir Fuel	ng unit(s):	Baseboar d Heating Electric		
21c. Installation and vocabilion 21d. Viewed in operat		M N		
21e. Combustion vent		NA		
Kitchen	-			
22. Walls and ceiling		М		
23. Floor condition an	ıd ceiling	М		
height 24. Evidence of damp staining	ness or	N		
25. Electrical outlets a fixtures	and	М		
26. Plumbing fixtures		М		
27. Water flow		М		
28. Window size/ oper area/ mechanical exha		М		
29. Condition of doors/ windows/ mech exhaust		М		
Living and Dining Roo	om(s)			
30. Walls and ceiling	` ,	М		
31. Floor condition an height	d ceiling	М		
32. Evidence of damp staining	ness or	N		
33. 目ectrical outlets a fixtures	and	М		
34. Window size and o	openable	М		
35. Window and door	condition	М		
Hallways, Stairs and E	ntries			
36. Walls, ceilings, flo	ors	М		
37. Evidence of damp staining	ness or	N		
38. Stairs and handrai	ls to	В	38. low handrail & ends no	ot returned to wall

Evaluator: Doug Hastings Cities' Inspection Service

upper floors

39. Electrical outlets and

40. Window and door conditions M

1880 MONTREAL AVE Sep 4, 2019 Page # 4

Hazardous Condition	B: Below Minim	um	C: See Comments	M: Meets Minimum
Yes	N: No		NV: Not Visible	NA: Not Applicable
Smoke Detectors	-		·	
41a. Present		Υ		
41b. Properly Lo	cated	Y		
41c. Hard-Wire		Υ		
Bathroom(s)				
<ul><li>42. Walls and ceiling</li><li>43. Floor condition and ceiling height</li><li>44. Evidence of dampness or staining</li></ul>		М		
		М		
		N		
45. 目ectrical out	lets and	В	45. inoperable baseme	ent sink outlet
fixtures 46. Plumbing fixtures		М		
47. Water flow		M		
48. Windows size	a/ onenable	M		
area/ mechnical e	•	IVI		
49. Condition of		M		
windows/ doors/   exhaust	mecnanical			
Sleeping Room(s)				
50. Walls and ceilings		М		
51. Floor condition	-	M		
ceiling height	o, a. oa aa	IVI		
52. Evidence of c	lampness or	N		
staining 53. Eectrical out	lets and	М		
fixtures	.oto and			
54. Window size	and openable	В		evel south bedroom windows
area 55. Window and	door condition	М	(not egress sized)	
Enclosed Porches and Other Roo				
56. Walls, ceiling condition	and floor	М		
57. Evidence of c	lampness or	N		
staining	lote and	B.4		
58. Electrical outlets and fixtures		М		
59. Window and	door condition	M		
Attic Space				
60. Roof boards	and rafters	М	60. limited view	
61. Evidence of c	lampness or	NV	- -	
staining 62. Electrical wiring/outlets/fixtures				
		NV		
63. Ventilation	v (n) 69	NV		
Exterior Space		-		
64. Foundation		М		
65. Basement/ce	llar windows			
65. Basement/ ce		M		
(:(:   1)	\			

1880 MONTREAL AVE Sep 4, 2019

М

Evaluator: Doug Hastings Cities' Inspection Service

66. Drainage (grade)

Report Rating Key (Where there are multiple rooms to a category, the Evaluator must specify the room to which a Comment is related				
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum	
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable	

67. Exterior walls M 68. Doors М (frames/storms/screens) 69. Windows М (frames/ storms/ screens) 70. Open porches, stairways and 70. settled side door concrete & high step rise / no deck(s) garage step handrail 71. Cornice and trim(s) M 72. Roof structure and covering M 73. Gutters and downspouts М 74. Chimney(s) М 75. Outlets, fixtures and service М entrance Garage(s)/ Accessory Structure(s) 76. Roof structure and covering 77. Wall structure and covering M 78. Slab condition В 78. cracked & settled concrete 79. Garage door(s) М 80. Garage opener(s) Υ 81. Electrical wiring, outlets and 81. missing outlet & switch cover plate fixtures Fireplace/ Woodstove 82. Number of Units 1 83. Dampers installed NA 84. Installation М 85. Condition М Insulation 86a. Attic Insulation: Present Υ 86b. Attic Insulation: Type Mixed 86c. Attic Insulation: Depth 12-15 inches 87a. Foundation Insulation: NV Present 87b. Foundation Insulation: NV Type 87c. Foundation Insulation: NV Depth 88a. Knee Wall Insulation: Υ Present 88b. Knee Wall Insulation: Type 88c. Knee Wall Insulation: Depth 0-3 inches

1880 MONTREAL AVE Sep 4, 2019

**Foam** 

0-3 inches

Evaluator: Doug Hastings Cities' Inspection Service

Present

89a. Rim Joist Insulation:

89b. Rim Joist Insulation: Type

89c. Rim Joist Insulation: Depth

Report Rating Key (Where there as	n to which a Comment is related)		
H: Hazardous Condition	B: Below Minimum	C: See Comments	M: Meets Minimum
Y: Yes	N: No	NV: Not Visible	NA: Not Applicable

# General

90. Carbon Monoxide Alarm М

General Comments

1880 MONTREAL AVE Sep 4, 2019 Evaluator: Doug Hastings Cities' Inspection Service Page # 7

#### **LEGAL NOTICES:**

Chapter 189 of the Saint Paul Legislative Code requires all single family, duplex, condo, townhouse and co-op homes for sale in the city to have a Truth-in-Sale of Housing disclosure report prepared and available to prospective buyers. A Truth-in-Sale of Housing disclosure report must be done for Contract-For-Deed sales.

A Truth-in-Sale of Housing (TISH) Disclosure Report in the City of Saint Paul is intended to provide basic information to the home buyer and seller prior to the time of sale. Failure to obtain a Truth-in-Sale of Housing disclosure report or failure to make that disclosure report available to prospective buyers, is a violation of law and is punishable as a misdemeanor carrying up to 90 days in jail and/or a \$1,000.00 fine.

A valid Truth-in-Sale of Housing disclosure report must be conspicuously displayed at the premises for all prospective buyers. TISH disclosure reports are also available online: https://online.stpaul. gov/ web/ portal/ public- search

- This report WILL NOT be used to enforce the requirements of the Legislative Code; however, this evaluation form will be used to determine if there is compliance with the requirements for a hardwired smoke detectors.
- This TISH report is based on the current Truth-in-Sale of Housing Evaluator Guidelines and is based upon different standards than the lender, Federal Housing Administration (FHA) or Veterans Administration (VA).
- This TISH is not warranted, by the City of Saint Paul nor by the evaluator for the condition of the building component, nor of the accuracy of this report.
- This TISH report covers only the items listed on the form and only those items visible at the time of the evaluation.
- The Evaluator is not required to operate the heating plant (except during the heating season), use a ladder to observe the condition of the roofing, disassemble items or evaluate inaccessible areas.
- This TISH report is valid for one year from the date of issue and only for the owner named on this
- If this building is used for any purpose other than a single family dwelling, it may be illegally zoned. To help you determine legal uses under the zoning ordinance, contact the Zoning Administrator at (651) 266-9008.
- Automatic garage doors should reverse upon striking an object. If it does not reverse, it poses a serious hazard and should be repaired or replaced immediately.
- All single family residences in Saint Paul must have at least one smoke detector connected to the electrical system (hard-wired). The detector must be located near sleeping rooms. For more information call Fire Prevention, (651)228-6230. (Saint Paul Legislative Code, Chapter 58.)
- Rainleaders connected to the sanitary sewer system must be disconnected. For more information call Public Works, Sewer Utility, and (651)266-6234.
- A house built before 1950 may have lead paint on/in it. If children ingest lead paint, they can be poisoned. For more information call Ramsey County Public Health, (651)292-6525.
- Neither the City of Saint Paul nor the Evaluator is responsible for the determination of the presence of airborne particles such as asbestos, noxious gases such as radon, or other conditions of air quality that may be present, nor the conditions which may cause the above.

Questions regarding this report should be directed to the evaluator. If you desire a reinspection and amended report, please contact your evaluator. They will perform a reinspection and file an amended report with the City of Saint Paul. The TISH evaluator may charge for this reinspection. Complaints regarding this report should be directed to Department of Safety and Inspections, Truth-in-Sale of Housing Program, Phone 651-266-8989.

1880 MONTREAL AVE Sep 4, 2019 Evaluator: Doug Hastings Cities'

Inspection Service

#### **Evaluator Statement:**

I hereby certify I prepared this report in compliance with the Saint Paul Evaluator Guidelines, City of Saint Paul City Ordinance 189 and all other applicable policies and procedures of the Truth- in\_Sale of Housing Board. I have utilized reasonable and ordinary care and diligence and I have noted all conditions found that do not conform to the minimum standards of maintenance. The report covers only those problems listed and reasonably visible at the time of my evaluation and does not warrent future useful life of any house component or fixture. I have included all required information pages with this report. Evaluator Name: Doug Hastings Cities' Inspection Service

Phone: Work: 952-892-0490 Evaluation Date: Sep 4, 2019

1880 MONTREAL AVE
Sep 4, 2019
Evaluator: Doug Hastings Cities'
Page # 9

Inspection Service